

## Sto Corp.


3800 Camp Creek Parkway Building 1400, Suite 120 Atlanta, GA 30331 Tel: 404-346-3666 Toll Free: 1-800-221-2397 Fax: 404-346-3119 www.stocorp.com

## **Tech Hotline**

## No. 0403-BSc

## **Critical Detail Checklist for Wall Assemblies**

Water intrusion into wall assemblies has become a growing concern in the construction industry, yet water intrusion can be prevented simply by following sound construction practices that are required by model building codes. The list of details below illustrates some of the key areas of construction to pay attention to when designing, detailing or constructing walls.



It has been said that, "As much as 90 percent of all water intrusion problems occur within 1 percent of the total building exterior surface area. The 1 percent of the structure's façade contains the terminations and transition detailing that all too frequently lead to envelope failures." <sup>1</sup> By paying close attention to construction details at cladding terminations, water intrusion can be prevented and building durability enhanced.

1. Waterproofing the Building Envelope, Kubal, Michael, T. (New York, 1993), p. 4.